


ALLQD S = -Q5DZ = 2PI, Q5IC = 0, XBDZ = 0.004, YBDZ = 0.138, RI31 = -0.1, RI32 = 0.0

CUTS.CSP

Point S
Min P

DP36

5-MAY-91 11:53







ALLQD'S = -Q5DZ = 2PI, Q5IC = 0, XBDZ = 0004, YBDZ = 0138, R131 = -0.1, R132 = 0.0

DRSG

GUTS.CSP 11

Points
in p

5-MAY-91 11:54




ALL Q4D S = -Q5DZ = 2PI, Q5IC = 0, XBDZ = -.0004, YBDZ = -.0138, RI31 = 0.1, RI32 = 0.0

DRSG

GUTS.CSF

Port 1

5-MAY-91 11:51





ALLQ4D'S = -Q5DZ = 2P1.Q5IC = 0.XBDZ = -.0004.YBDZ = -.0138.RI31 = 0.1.RI32 = 0.0

DRG

GUTS.CSP '9

Print /
Hing P

5-MAY-91 11:52



ALLQ4D'S = -Q5DZ = 2P1.Q51C = 0.R131 = R132 = 707.XBDZ = 00974.YBDZ = -.0212


Part 2

GUTS.CSI

HP40P

DP3G





6-MAY-91 09:55



ALLQ4D'S = -Q5DZ=2P1,Q5IC=0,R131=R132=.707,XBDZ=.00974,YBDZ=-.0212

Point 2
H199P

DRSG




ALLQ4D S = -Q5DZ = 2PI, Q51C = 0, R131 = R132 = 0.707, XBDZ = -YBDZ = 0.009739878

GUTS.C 5

Point 2
H179r

DR36

9-MAY-91 07:18





ALLQ4D S=-Q5DZ=2PI,Q5IC=0,R131=R132=707,XBDZ=-YBDZ=.009739878

DP5G

Print 2
Hinger

GUTS.CSF

6-MAY-91 09:36



ALL Q4D S = -Q5DZ = 2PI, Q5IC = 0, R131 = R132 = 0.707, XBDZ = -YBDZ = 0.009739878

GUTS.C 5

Point 2
HIN9

DP5G

9-MAY-91 07:34